Scout 2
Next Generation Economical Mediation/Concentration Device Release Notes

Version 2.01
January 2009



Part Number 65-000025

© 2009 by Kentrox, Inc. All rights reserved.

Copyright © 2009 by Kentrox, Inc. All Rights Reserved. The material discussed in this publication is the proprietary property of Kentrox, Inc. Kentrox retains all rights to reproduction and distribution of this publication.

Kentrox is a registered trademark of Kentrox, Inc. Applied Innovation, Applied Innovation Inc., the AI logo, and other names are the intellectual property of Kentrox. All other product names are trademarks or registered trademarks of their respective owners.

Information published here is current as of this document's date of publication, but is subject to change without notice. You may verify product information by contacting our headquarters. Kentrox is an Equal Opportunity/Affirmative Action employer.

Kentrox, Inc.
5800 Innovation Dr.
Dublin, Ohio USA 43016-3271
Toll Free: (800) 247-9482
International: +1 (614) 798-2000
Fax: +1 (614) 798-1770

Scout 2
Next Generation Economical Mediation/Concentration Device Release Notes

Version 2.01
January 2009

These release notes document a change for the Scout 2 next generation economical mediation/concentration device version 2.01. This document also provides software update instructions and a compatibility matrix for Scout 2 version 2.01.

Instructions for use of this product are detailed in the *Scout 2 Next Generation Economical Mediation/Concentration Device*.

Change

Scout 2 version 2.01 includes the following change:

- Discrete Alarms Display Correct Status After Reboot (Issue 67389)

Discrete Alarms Display Correct Status After Reboot

Description: In Scout 2 version 2.00, some discrete alarms displayed an incorrect status after reboot.

Resolution: Discrete alarms now display the correct status after reboot.

Software Update Instructions

The following sections provide information on updating your Scout 2 software to version 2.01.

Obtaining the Software

Scout 2 version 2.01 software consists of the following file:

`35sct201.img`	This is a binary file containing the Scout 2 version 2.01 software image.

If you need assistance with obtaining the software, please contact your sales representative or Kentrox Technical Support.

Updating the Software Using an FTP Session

To update the Scout 2 software to version 2.01 using an FTP session:

1. Using an FTP utility, transfer the updated software image (`35sct201.img`) to Scout 2 using binary mode.
2. At the prompt, enter:

   `site update 35sct201.img boot.img`

   Tip: Some FTP clients require that you enter **`quote`** before this command. For example, **`quote site update 35sct201.img boot.img`**.

   When the update is complete, the following message appears:

   `Copy complete.`
3. Enter:

   `site reset`

   Tip: Some FTP clients require that you enter **`quote`** before this command. For example, **`quote site reset`**.

   Scout 2 resets and then comes back online.
4. Access and log into Scout 2.
5. At the prompt, enter the destination name:

   `ai`
6. Enter:

   `show version`

   A screen similar to the following appears:

```
[AIscout2]show version
Version 35SCT201.000001 created on 2008-12-18 at 14:41:10
Boot Loader Version 335BL100.000003
[AIscout2]
```

   Verify that the correct software version is running on Scout 2. If it is, the version information on the screen should begin with `35SCT201`.

Updating the Software Using a Shell Connection

To update the Scout 2 software to version 2.01 using a shell connection:

1. Using an FTP utility, transfer the updated software image (`35sct201.img`) to Scout 2 using binary mode.
2. At the prompt, enter the destination name:

   `ai`
3. Enter:

   `update 35sct201.img boot.img`
4. Enter:

   `reset`

   The following message appears:

   ```
   Are you SURE you want to reset the system? (y/n)
   ```
5. Enter **`y`**.

   Scout 2 resets and then comes back online.
6. Access and log into Scout 2.
7. At the prompt, enter the destination name:

   `ai`
8. Enter:

   `show version`

   A screen similar to the following appears:

   ```
   [AIscout2]show version
   Version 35SCT201.000001 created on 2008-12-18 at 14:41:10
   Boot Loader Version 335BL100.000003
   [AIscout2]
   ```

   Verify that the correct software version is running on Scout 2. If it is, the version information on the screen should begin with `35SCT201`.

Compatibility Matrix

The following list specifies the versions of AppliedView AI product element management system that are compatible with Scout 2 version 2.01. Any versions not listed are not compatible with Scout 2 version 2.01.

AppliedView 4.00	AppliedView 4.30
AppliedView 4.10	AppliedView 4.40
AppliedView 4.20	AppliedView 4.50